Scope of	Work for Property Loc	ated at	:	3918 West Galena Street		
	Property is: Single Fan	nily 🗹	Duplex	☐ Other ☐		
Date:	3/10/2014					
take no respo	onsibility for problems discovered	after the in	spection da	s. The City of Milwaukee, the Redevelop te, or for omissions through error or over leral Block Grant or HOME programs.	•	
Exterior (	Condition Report					
Location Site	Required Work Landscaping	n/a ✓	Yes 🗌	Note/Comments Self Help	Cost \$	
	Steps/Handrails	n/a	Yes 🗸	Front service stairs	\$ 40	0.00
	Service walks	n/a ✓	Yes 🗌		\$	
	Fencing	n/a ✓	Yes		\$	
	Parking	n/a ✓	Yes 🗌		\$	
	Retaining walls	n/a ✓	Yes 🗌		\$	
	Other	n/a 🗌	Yes $\square$		\$	
	Other	n/a	Yes 🗌		\$	
Garage	Singles: repair	n/a 🗌	Yes 🗌		\$	
	Shingles: Roof over existing	n/a	Yes 🗌		\$	
	Shingles:Tear off & re-roof	n/a	Yes 🗌		\$	
	Gutters/downspouts	n/a	Yes 🗌		\$	
	Flashing	n/a 🗌	Yes 🗌		\$	
	Eaves	n/a 🗌	Yes 🗌		\$	
	Siding	n/a	Yes 🗌		\$	
	Doors	n/a	Yes 🗌		\$	
	Windows	n/a 🗌	Yes 🗌		\$	
	Slab	n/a	Yes		\$	
	Paint	n/a	Yes 🗌		\$	
	Electrical	n/a	Yes 🗌		\$	
_	Other	n/a 🗌	Yes 🗌		\$	
Porches	Roof	n/a ☑	Yes 🗌		\$	
	Deck-upper	n/a ✓	Yes 🗌		\$	
	Decklower	n/a ✓	Yes 🗌		\$	
	Steps/handrails	n/a 🗌	Yes ✓	missing riser	\$ 2	5.00
	Ceiling	n/a ✓	Yes 🗌		\$	
	Guardrails	n/a ✓	Yes 🗌		\$	
	Structural	n/a ✓	Yes 🗌		\$	
	Paint	n/a ✓	Yes 🗌		\$	

n/a 🗌 Yes 🗌

\$

Other

## House

Chimney	n/a 🗌 Yes 🗹 <b>Tuck poitn and flash</b>	\$ 450.00
Shingles: repair	n/a ☑ Yes 🗌	\$ 
Shingles: Roof over existing	n/a ☑ Yes 🗌	\$ 
Shingles:Tear off & re-roof	n/a ☐ Yes ☑	\$ 7,000.00
Gutters/downspouts	n/a ☐ Yes ☑	\$ 900.00
Flashing	n/a 🗸 Yes 🗌	\$
Eaves	n/a ☑ Yes 🗌	\$ 
Siding	n/a ☑ Yes 🗌	\$ 
Storm Doors	n/a ☑ Yes 🗌	\$ 
Prime ("main") Doors	n/a 🗸 Yes 🗌	\$
Storm Windows	n/a ☑ Yes 🗌	\$ 
Prime ("main") Windows	n/a ☑ Yes 🗌	\$ 
Paint	n/a  Yes  Trim and foundation	\$ 1,500.00
Foundation	n/a ☑ Yes 🗌	\$ 
Electrical	n/a ☑ Yes □	\$ 
Other	n/a Yes V Handset front door	\$ 75.00
Other	n/a 🗌 Yes 🗌	\$ 
Other	n/a 🗌 Yes 🗌	\$ 
Other	n/a 🗌 Yes 🗍	\$ 

Exterior: Estimated Cost:\* \$
\*average contracted cost. Actual costs may vary. Self help will reduce the amount.

10,350.00

Interior Co	ondition Report						
	<b>Unit:</b> Entire unit (single family) Upper unit of duplex	✓				Lower unit of duplex U	
Mechanical Heating	Required Work	_					
	Repair/replace boiler	n/a	<b>✓</b>	Yes			\$ 
	Repair radiation	n/a	<b>✓</b>	Yes			\$ 
	Repair/replace furnace	n/a	<b>✓</b>	Yes			\$ 
	Repair ductwork	n/a		Yes	J		\$ 50.00
	Replace thermostat	n/a	<b>~</b>	Yes			\$
	Repair/replace grilles	n/a	<b>V</b>	Yes			\$
Electrical	Tune boiler/furn. insp ht exchang	n/a	<b>V</b>	Yes			\$
2.000.100.	Repair/replace receptacles	n/a		Yes	<b>V</b>		\$ 100.00
	Repair/replace switches	n/a		Yes	<b>V</b>		\$ 100.00
	Repair/replace fixtures	n/a		Yes	<b>V</b>		\$ 250.00
	Install outlets and circuits	n/a	<b>V</b>	Yes			\$
	Install outlets and circuits	n/a	<b>V</b>	Yes			\$
	Install outlets and circuits	n/a	<b>V</b>	Yes			\$
	Install outlets and circuits	n/a	<b>V</b>	Yes			\$
	Upgrade service	n/a	<b>V</b>	Yes			\$
	Other	n/a		Yes			\$
	Other	n/a		Yes			\$
Plumbing	Repair/replace kitchen sink	n/a	<b>~</b>	Yes			\$
	Repair/replace kitchen sink fauce	n/a		Yes	<b>V</b>	Repair	\$ 75.00
	Repair/replace tub	n/a	<b>V</b>	Yes			\$
	Repair/replace tub faucet	n/a	<b>V</b>	Yes			\$
	Repair/replace toilet	n/a	<b>~</b>	Yes			\$
	Repair/replace lavatory	n/a	<b>~</b>	Yes			\$
	Repair/replace lavatory faucet	n/a	<b>~</b>	Yes			\$
	Repair/replace wash tub	n/a	<b>V</b>	Yes			\$
	Repair/replace wash tub faucet	n/a	<b>V</b>	Yes			\$
	Unclog piping:	n/a	>	Yes			\$
	Repair drain/waste/vent piping	n/a	<b>/</b>	Yes			\$
	Repair water piping	n/a	<b>V</b>	Yes			\$ 
	Repair/replace water heater	n/a	<b>V</b>	Yes			\$
	Other	n/a		Yes		_	\$ 

n/a 🗌 Yes 🗌

Other

Windows									
	Replace broken glass	n/a	<b>V</b>	Yes			\$		
	Repair or replace sash	n/a	<b>V</b>	Yes			\$		
Doors									
	Repair or replace doors	n/a	V	Yes			\$		
	Repair or repl. locks/latches	n/a	<b>V</b>	Yes		Self Help	\$		
Walls/Ceiling									
	Repair or repl. @ defective	n/a		Yes	1		\$	300.00	
Paint									
	Repair or repl. @ defective	n/a		Yes	<b>V</b>		\$	100.00	
Fire Safety									
	Install smoke/CO alarm:bsmt.	n/a		Yes	<b>✓</b>	Self Help	\$	50.00	
	Install smoke/CO alarm: 1st flr.	n/a		Yes	<b>V</b>	Self Help	\$	50.00	
	Install smoke/CO alarm: 2nd flr.	n/a		Yes	J	Self Help	\$	50.00	
Handrails	Repair/replace defective	n/a		Yes	<b>V</b>	Self Help	\$	125.00	
Stairs						·			
	Repair defective	n/a		Yes	J	Repair	\$	150.00	
Floors	Repair defective	n/a		Yes	<b>7</b>	Powder Room	\$	400.00	
Other							· ·		
		n/a		Yes			\$		
		n/a		Yes			\$		
		n/a		Yes			\$		
		n/a		Yes			\$		
						Interior: Estimated Cost:	\$	1,800.00	
						Total Exterior and Interior Cost:*	\$	12,150.00	
	*average contracted cost. Actual costs may vary. Salf help will reduce the amount								

Inspected by: Andy Yeager Date: 3/10/14

## Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

## **Important Information Regarding Permits**

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located on the first floor of 841 N. Broadway.

<sup>\*</sup>average contracted cost. Actual costs may vary. Self help will reduce the amount.